



# STORAGE OF SAFETY TOOLS

- Always transport your safety tools in such a way that the insulation cannot suffer any damage
- Check that the insulation is not damaged each time before using the tool; defective tools must not be used and should be stripped of all insulation
- Keep your safety tools clean and dry
- When working with cutting nippers or when working above head height, wear goggles
- Ensure that the workplace, when you are working on live equipment, is clean and tidy
- Use protective clothing and safety equipment (e.g. safety gloves, cover cloths and safety sleeves) above all in confined spaces
- Only use tools of the right dimensions – this prevents the tool slipping on the workpiece and undesired contact with the non-insulated parts
- Ensure that released part and the end of cables which you have cut off do not fall onto live parts.



**JBS RECOMMENDS THE USE OF APPROPRIATE P.P.E.  
AND CORRECT LIFTING PROCEDURES**

(P.P.E. – Personal Protective Equipment)